



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 041708360

Customer ID: SMGS78B

Customer PO:

Project ID: Oroville EM OP

Attention: Dave Beadle, CIH
Safety Management Systems
460 Glen Drive
Industrial Hygiene Trailer
Oroville, CA 95966
Project: 2017.03.26 Perimeter Samples (Oroville EM OP)

Phone: (661) 699-9375
Fax:
Received Date: 3/28/2017 8:00 AM
Analysis Date: 03/28/2017 - 03/29/2017
Collected Date: 03/26/2017

Test Report: Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by CARB-Modified AHERA

Sample	Location	Volume (Liters)	Area Analyzed (mm ²)	Non Asb	Asbestos Types	#Structures		Analytical Sensitivity (S/cc)	Asbestos Concentration	
						≥0.5μ < 5 μ	≥5μ		(S/mm ²)	(S/cc)
0326-OFD-PMT-01 041708360-0001	AM Perimeter- Intake Yard	2411.10	0.1720	0	None Detected			0.0009	<5.80	<0.0009
0326-OFD-PMT-02 041708360-0002	AM Perimeter- Upper Lookout Entry	2112.90	0.1850	0	None Detected			0.0010	<5.40	<0.0010
0326-OFD-PMT-03 041708360-0003	AM Perimeter- Upper Lookout Trailer	2372.20	0.1720	0	None Detected			0.0009	<5.80	<0.0010
0326-OFD-PMT-04 041708360-0004	AM Perimeter- Canyon Drive	2339.00	0.1720	0	None Detected			0.0010	<5.80	<0.0010
0326-OFD-PMT-05 041708360-0005	PM Perimeter- Intake Yard	2549.30	0.1580	0	None Detected			0.0010	<6.30	<0.0010
0326-OFD-PMT-06 041708360-0006	PM Perimeter- Upper Lookout Entry	2447.20	0.1580	0	None Detected			0.0010	<6.30	<0.0010
0326-OFD-PMT-07 041708360-0007	PM Perimeter- Upper Lookout Trailer	2812.60	0.1450	0	None Detected			0.0009	<6.90	<0.0009
0326-OFD-PMT-08 041708360-0008	PM Perimeter- Canyon Drive	2629.20	0.1580	0	None Detected			0.0009	<6.30	<0.0009
0326-OFD-PMT-FB1 041708360-0009	Field Blank 1	0.00	0.1320	0	None Detected			N/A	<7.60	N/A
0326-OFD-PMT-FB2 041708360-0010	Field Blank 2	0.00	0.1320	0	None Detected			N/A	<7.60	N/A

Analyst(s)

Darrah Johnson-McDaniel (7)
Matthew Dare (3)

Benjamin Ellis, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMSL is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. Samples received in good condition unless otherwise noted. The test results meet the requirements of NELAC unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial Report From: 03/29/2017 11:38:11